



Simplified Instruction Manual

Refer to the instruction manual on the A&D home page  
URL: <http://www.aandd.co.jp/>

1WMPD4002992C

This Manual

- This manual describes how the product works and how to get the most out of it in terms of performance. Read this manual thoroughly before using the product and keep it at hand for future reference.
- Product specifications are subject to change without any obligation on the part of the manufacturer to notify of changes.
- This manual is subject to change without notice at any time to improve the product. No part of this manual may be photocopied, reproduced, or translated into another language without the prior written consent of the A&D Company, limited.
- Do not attempt to repair, modify or disassemble the product. Doing so will void the warranty.

©2018 A&D Company, Limited All rights reserved.  
3-23-14 Higashi-Ikebukuro, Toshima-ku, Tokyo 170-0013, JAPAN  
Telephone: [B1] (3) 5391-6132 Fax: [B1] (3) 5391-6148

1. Cautions

1.1. Installation and Precautions

Before use, confirm the following articles for safe operation.

- Avoid vibration, shock, extremely high temperature and humidity, direct sunlight, dust, splashing water, air containing salt or corrosive gases, places where inflammable gases are present.
- The operating temperature is -10°C to +50°C (14°F to 122°F).
- Ground the module.
- Keep cables away from power cables and other sources of electrical noise. Use a stable DC24 V power source that does not include step down voltage and noise.
- Do not share the earth ground line and power line with other electrical power equipment.
- When extending the load cell cable, separate it from the power cable and electrical cables with much noise.
- Do not turn on the module until installation is complete. The module is not equipped with a switch to turn off.
- After the installation is complete, take off the protective cover prior to turning on the AD-4430C.
- Use a shielded load cell cable.
- Do not connect more sensors than the allowable number noted in the specifications.

1.2. Cautions During Use


The AD-4430C is a precision instrument that measures micro-volt output from load cell. Prevent noise sources such as power lines, radios, electric welders or motors from affecting the instrument.

- Do not disassemble the AD-4430C.

2. General Specifications


Voltage requirement	DC 24 V +10%, -15%
Power requirement	6 W Max.
Load cell excitation voltage	DC 5 V 350 Ω sensor. Up to four sensors can be connected
Operating conditions	-10 °C to +50 °C, Max 85 %RH (no condensation)
External dimensions	35.3 × 110.0 × 101.3 mm (W×H×D)
Mass	Approximately 200 g
Main display	The monitor displays measurement data and settings with 7 segments of 5 digits and negative sign. The decimal point is specified at the function table.
Accessory	CC-Link connector x 1, made by 3M: 35505-6000-BOM GF

3. Panels




3.1. Power Supply Connector

+24 V	DC +24 V terminal.
0 V	DC 0 V terminal.
FG (SHLD)	Ground terminal. (Connector shield of all are connected inside.)




3.2. Sensor Terminals of Load Cell

SIG-	The (-) input terminal of signal that is outputted from load cell.
SIG+	The (+) input terminal of signal that is outputted from load cell.
EXC-	The (-) output terminal for load cell excitation voltage (-).
SEN-	The (-) input terminal for sensing input (-). (When performing the 4-wire connection, connect between EXC- and SEN-.)
SEN+	The (+) input terminal for sensing input (+). (When performing the 4-wire connection, connect between EXC+ and SEN+.)
EXC+	The (+) output terminal for load cell excitation voltage (+).
SHLD	Connect shield of load cell cable.





- Connections  
When connecting and removing the cables, push the buttons with a driver etc. We recommend use of pole crimp terminals for the tips of cables.



3.3. Control I/O, Standard serial output, CC-Link connector and USB connector

- Terminals of control I/O is isolated from load cell and power supply (POWER). Supply D.C. +24 V between PWR+24V terminal and COM terminal.
- Standard serial output (C.L.) circuit is isolated from other terminals.
- Use standard CC-Link connector.
- Use standard Micro - B USB connector.



3.4. Status Indicator

LED	Description
G	Gross : LED lights when indicating gross value.
N	Net : LED lights when indicating net value.
H	Hold : LED lights when the hold function operates.
S	Stable : LED lights when the current weighing value is stable.
Z	Zero : LED lights when the weighing value is center zero.
X	This LED works by selected function at Fnc 04.

3.5. Key switches

Operation	Function
[F]	The function key works by selected function at Fnc 02 in weighing mode.
[ESC]	The escape key during numerical input and function mode.
[→]	"The zero key" to perform the zero operation in weighing mode. The key to change a selected item or move a flashed figure.
[↑]	"The tare key" that displays zero for net weighing. The key to select parameter or increase number in setting mode.
[ENT]	Press the key to turn on the display in standby (OFF mode). Press and hold the key to turn off the display in weighing mode. In the setting mode, this key to store new settings. "the enter key".
[ENT] + [F]	Proceeds to the function mode from the weighing mode.
[→] + [ENT]	Proceeds to the check mode from the function mode.
[F] + [ENT]	Proceeds to the calibration from standby (at OFF mode)

3.6. Operation Mode

- Function mode (In weighing mode, [ENT] + [F])  
The condition of the AD-4430C can be updated and be stored.
- Check mode (In function mode, [→] + [ENT])  
The mode to check the AD-4430C.
- Calibration mode (When display is turned off, [F] + [ENT])  
The mode to calibrate zero point and span of the AD-4430C using a mass or by inputting numerical value.

4. Calibration

The AD-4430C measures the voltage of the load cell and displays it. Calibration is the function used to adjust the AD-4430C so that the signal from the load cell is properly converted to mass.

- Specify "decimal point position (C-F 02)", "minimum division (C-F 03)" and "weighing capacity (C-F 04)" in function mode.
- "input voltage at zero calibration (C-F : 7)", "input voltage at span calibration (C-F : 8)" and "mass value against input voltage at span calibration (C-F : 9)" can be changed by the "span calibration using mass (C-F 05)" in calibration mode. These items can be also inputted using "digital span" in function mode.
- Perform stable measurement in the calibration to prevent measurement error.
- During a stable measurement, the S LED lights.
- The flashing decimal point means "no weighing value" in calibration mode.
- When [C-Er] and a number are displayed, an error has occurred. Refer to "Calibration Errors" for details.
- Before the calibration, turn on the AD-4430C more than 10 minutes so as to avoid temperature drift (change).

4.1. Span Calibration using Mass (C-F 05)

Perform the zero and span calibration by placing and removing the mass. When calibrating the AD-4430C for the first time, it is necessary to set a unit, decimal point, minimum division and weighing capacity in function mode beforehand.

- Step 1 When turning off the display using pressing and holding the [ENT] key, press the [F] key and the [ENT] key ([F] + [ENT] key). Then [C-R] of calibration mode is displayed.
- Step 2 Press the [ENT] key to enter calibration mode. [C-F 05] is displayed. When returning to weighing mode, press the [ESC] key.

4.1.1. Zero Calibration

- Step 3 Press the [ENT] key to display [C-R]. When skipping zero calibration, press the [↑] key and proceed to step 5.
- Step 4 Confirm that the [S] LED is lit and press the [ENT] key. Then [.....] is displayed for 2 seconds. When canceling span calibration and returning to weighing mode, press the [ESC] key twice.

4.1.2. Span Calibration

- Step 5 When [C-F 05] is displayed, press the [ENT] key. The current calibration weight value is displayed. A figure flashes. Specify a new value using the [→] and [↑] keys. When canceling span calibration and returning to weighing mode, press the [ESC] key twice.
- Step 6 Place a mass on the weighing pan. Confirm that the [S] LED is lit and press the [ENT] key. Then [.....] is displayed for 2 seconds.
- Step 7 When [C-Er] is displayed, remove the mass from the weighing pan. When repeating span calibration, press the [↑] key.
- Step 8 Press the [ESC] key. Then [C-F 05] is displayed and calibration data is stored in the nonvolatile memory of the AD-4430C.
- Step 9 Press the [ESC] key to return to weighing mode.

4.2. Digital Linearization (C-F 06)

Digital linearization is the non-linearity compensation function that can rectify or reduce linearity deviation between zero point and weighing capacity.

- Up to four points can be specified except zero. (Refer to C-F 04)  
Relationship of points : Zero = Lnr 0 < Lnr 1 < Lnr 2 < Lnr 3 < Lnr 4
- The high-order correction curve is used so that zero point and individual points are arranged in a straight line.
- Digital linearization includes span calibration.

- Step 1 When turning off the display using pressing and holding the [ENT] key, press the [F] key and the [ENT] key ([F] + [ENT] key). Then [C-R] of calibration mode is displayed. Press the [ENT] key to display [C-F 06].
- Step 2 Press the [↑] key to select [C-F 06] and press the [ENT] key to enter digital linearization.
- Step 3 [Lnr 0] of the zero point is displayed.
- Step 4 While [S] LED is displayed, press the [ENT] key to store the weighing value. Then [.....] is displayed for 2 seconds.
- Step 5 When displaying [Lnr 1], press the [ENT] key to select a weight value. Specify it using the [→] and [↑] key.
- Step 6 Place the weight on the pan. While [S] LED is displayed, press the [ENT] key to store the weighing value. Then [.....] is displayed for 2 seconds.
- Step 7 [Lnr 2] is displayed. Repeat the same operation as Step 5 and Step 6 at the second point.
- Step 8 [Lnr 3] is displayed. Repeat the same operation as Step 5 and Step 6 at the third point.
- Step 9 [Lnr 4] is displayed. Repeat the same operation as Step 5 and Step 6 at the fourth point.
- Step 10 [C-Er] is displayed. Press the [ESC] key to store new parameters into nonvolatile memory and display [C-F 06].
- Step 11 Press the [ESC] key to return to weighing mode. Remove all of weight from the pan.

4.3. Calibration Errors (C-Er)

Display	Cause	Treatment
C-Er 1	The display resolution (maximum capacity / minimum division) exceeds the specified value.	Make the minimum division greater or make the weighing capacity smaller. The specified value depends on specifications of the weighing system.
C-Er 2	Voltage at zero calibration exceeds in the positive direction.	Check the load cell rating and connection. When nothing is wrong with the rating and connection, adjust the load cell output. When the load cell or A/D converter may be the cause of error, confirm this by using the check mode.
C-Er 3	Voltage at zero calibration exceeds in the negative direction.	Check the load cell rating and connection. When nothing is wrong with the rating and connection, adjust the load cell output. When the load cell or A/D converter may be the cause of error, confirm this by using the check mode.
C-Er 4	The value of the calibration weight exceeds the maximum capacity.	Use an appropriate calibration weight and calibrate again.
C-Er 5	The value of the calibration weight is less than the minimum division.	Use an appropriate calibration weight and calibrate again.
C-Er 6	The load cell sensitivity is not sufficient.	Use a load cell with higher sensitivity or make the minimum division greater.
C-Er 7	Voltage at span calibration is less than voltage at the zero point.	Check the load cell connection.
C-Er 8	The load cell output voltage is too high when the mass of maximum capacity is weighed.	Use a load cell with a greater rating or make the weighing capacity smaller.

